MY WATER HAS BLACK PARTICLES												
LIKELY	HEALTH	OTHER CLUES &	CONFIRM	POSSIBLE	LICENSE REQUIRED	STATE	MORE					
PROBLEM	CONCERN?	CONSIDERATIONS	IT	FIXES	FOR FIX?	FUNDS?	INFO					
Manganese	Possibly, if	Do you have black	Test your	Install a Dept.	Yes, treatment devices	No	UWSP Well					
or	levels are	specks in your	water for	of Safety and	must be installed by		<u>Water</u>					
Manganese	very high.	water? When you	manganese	Professional	<u>licensed plumbers;</u> or		<u>Quality</u>					
and Iron	Manganese	rub the specks	and iron.	Services	in some cases may be		<u>Viewer</u>					
See	is a	between your fingers,	Contact a	<u>approved</u>	installed by the							
<u>Iron in</u>	necessary	does it leave a black	laboratory	<u>water</u>	owner/occupant of a		<u>Center for</u>					
<u>Drinking</u>	mineral for	powder? Does your	certified by	treatment	single family private		<u>Watershed</u>					
<u>Water</u>	good health	laundry get dark	DNR to test	<u>device</u> -	residence. See		<u>Science and</u>					
brochure.	and there is	stains?	<u>for</u>	from the search dropdown,	plumbing license laws.		Education,					
	not a primary		<u>manganese</u>	select products;			<u>UW-Stevens</u>					
	drinking		and iron.	then from the	Be sure the treatment		<u>Point</u>					
	water standard for			type of product	device chosen is		L Inite d					
				dropdown, choose	capable of removing the amount of		<u>United</u> States					
	manganese. There is			plumbing	manganese and iron		<u>Geological</u>					
	however, a			products and	you have in your water.		Survey					
	nuisance			from the select			Guivey					
	standard for			product description			National					
	manganese.			dropdown,			Ground					
	Also, EPA			choose water			Water					
	has issued a			treatment			Association					
	health			device.								
	advisory for						Water					
	manganese.						<u>Systems</u>					
	See the						Council					
	Dept. of											
	Health <u>Fact</u>						<u>National</u>					
	Sheet for						Sanitation					
	<u>Manganese</u> .						Foundation					

MY WATER HAS BLACK PARTICLES, CONTINUED												
POSSIBLE	HEALTH	OTHER CLUES &	CONFIRM	POSSIBLE	LICENSE REQUIRED	STATE	MORE					
PROBLEM	CONCERN?	CONSIDERATIONS	IT	FIXES	FOR FIX?	FUNDS?	INFO					
Sand or Silt	No.	Is this a new well? Did	Fill a glass	For a new well:	Yes, <u>Well Drillers</u> are	No	Contact a					
from: an	Although	the driller develop the	or the	Let the water	required to develop the		licensed					
improperly	silt/sand is a	well properly? Was	bathtub,	run for a	well properly after		<u>Well Driller</u>					
developed	nuisance	the screen sized	and let the	couple days.	drilling.							
well; an	because it	properly to prevent fine	water sit	Sometimes this								
increase in	can shorten	materials from entering	for awhile.	will clear out the								
pumpage; a	the life of	the well?	Does sand	fine materials. If								
sandstone	water using		drop to the	this doesn't								
well with a	appliances	Did silt/sand increase	bottom?	work contact								
sloughing	and damage	in your water following		your driller and								
formation; or screen	your well	installation of a larger		request that he return to								
failure due to	pump.	pump? Did you recently install a water		develop the well								
excessive		fixture that uses large		and/or								
incrustation		amounts of water? If		determine what								
merustation		you are pumping more		is causing the								
		water than before from		sand problem.								
		a sandstone well.		Install a liner in	Yes, Well Drillers have	No						
		water can scour the		a sandstone	the knowledge and	110						
		open drillhole.		well.	equipment to install							
				A liner can seal	liners.							
		Is your well older?		off a sloughing								
		Has the sand		sandstone								
		increased gradually as		formation to								
		water production has		keep sand/silt								
		decreased? Maybe		out of the water.								
		the screen has		Replace the	Yes, <u>Well Drillers</u> have							
		become incrusted so		screen in a	the knowledge and							
		that water enters the		sand & gravel	equipment to replace							
		well at higher velocities		well; or install	well screens.							
		and has eroded larger		a screen if								
		holes in the screen.		there is none.								